



PROCEDURE ON HOW TO CLEAN ANIMALS BEDS AND OTHER EQUIPMENT

Spray the animal bed, monitoring equipment (blanket, temperature probe) and the table with the solution in the "red" spraying bottle

Let the solution act for 5-10 min

Spray everything again with water in the "blue" spraying bottle

Wipe off with paper towel